



MISURA SIZE	DN	BOX	MASTER BOX	ØP	I	l1	Ch	ØH	L	h	R	Kv	PN	Kg
1/2"	15	40	80	16	15	10	25	31	80,5	48	50	8,5	16	0,26
3/4"	20	20	40	21	16,3	12	31	38	91	51,5	50	17	16	0,38
1"	25	15	30	27	19,1	14	38	46	103,5	55	50	27	16	0,60

Limiti di temperatura: $-10^{\circ}\text{C} + 130^{\circ}\text{C}$ - Temperature range: $-10^{\circ}\text{C} + 130^{\circ}\text{C}$.